

## Hulihe'e Palace

John Canning & Co.'s expertise in plaster repair and restoration was essential for the successful restoration and repair of Hulihe'e plaster-over-lava-rock construction.

### PROJECT DETAILS

John Canning & Co. restored plaster at the historic Hulihe'e Palace.

The Palace, the former vacation home of Hawaiian royalty, is completely constructed out of lava rock.

Now a cultural museum, it was severely damaged by an earthquake in 2006. This caused significant structural damage and cracking in the lava rock.

### GALLERY



 [Project Summary PDF](#)

### BUILDING FACTS

 [Location: Kailua-Kona, HI](#)

 [Built: 1838](#)

 [Architect: John Adams Kuakini](#)

 [Style: Victorian](#)

 [Status: National Historic Landmark](#)

### SCOPE

- [Interior and Exterior Plaster Restoration](#)

### PROJECT TEAM

 [Architect: Mason Architects, Inc.](#)